

Building Safety Certificate

Letter No. 763

Date: 22.04.23

TO WHOM IT MAY CONCERN

Sub: Ground +3 floord of school building of Mount Litera Zee School, is running under Rohitaswa Educational Trust on Plot 1243, At-Patia, PO: Raghunathpur, Bhubaneswar, Khurda, Odisha – 751024.

This is to state that the structural design for the said building of Mount Litera Zee School, at Patia, Raghunathpur, Bhubaneswar, Odisha-751024 has been done by me. Confirming to the relevant IS code that work carried out at the site is structurally stable and safe for the purpose intended to the best of my knowledge.

E. Pitambarnath Sharma

Signature: Pitambarnath Sharma

(B.E.-CIVIL)

Reg. No.: RTA/OTP (C. E.) 2487018

Name: Pitambarnath Sharma

Designation: Civil Architect

PROFORMA FOR THE SAFETY OF SCHOOL BUILDING

PART-I

(To be filled by the Head of School/ Institute)

1. **Name of the School** Mount Litera Zee School (Running under Rabhinswa Educational Trust)
2. **Location** Plot 1243, Raghunathpur, Patia, P.S - Nandankanan, Dist - Khurda, Odisha State, Pin - 751024
3. **Plot Area** 1 Acres
4. **Plinth Area** Total 2240 sq m (Ground Floor-560 x 1st floor-560 x 2nd floor-560 x 3rd floor-560)
5. **Number of Storey's** 0+3
6. **Year of Construction of Building** 2023
7. **If the building has not been constructed under the supervision of the qualified Engineer, the following details may be given:**
- a) **Name of the Engineer with qualification**
Dr. SATYENDRA KUMAR(B.Tech. Civil)
- b) **Address of Engineer-Nandan Villa Raghunathpur, Nandankanan Road, Bhubaneswar, Odisha, Pin 751024**
- c) **Set of Structural drawings used in the construction, if available:**
Detailed drawing as per item no. 12 attached
- d) **Name & Address of Architect with qualification**
Architect: Shri Sudhir Kumar(B.Tech. Archt) Plot No. 575, IRC Village, Bhubaneswar, Odisha 751015
8. **Whether the building has been constructed for the purpose**
- a) **School** YES
- b) **Residential purpose and converted for use as a School** NO
9. **Materials used for the roofs:**
- a) **R.C.C. Slabs - R.B.C. Slabs** YES
- b) **R.S. Joist & Battens** NO
- c) **Wooden Joists & Battens** NO
10. **Materials used for the walls**
- a) **Mud Mortar** NO
- b) **Cement Mortar** YES
- c) **Lime Mortar** NO
11. **Flooring**
- a) **Conglomerate:** YES
- b) **Terazzo** NO
- c) **Brick paving** NO
- A detailed drawing indicating dimensions of the rooms. Alongwith size and location of doors and windows. Attached**

Miyadarshevi Sanany

Signature with Stamp of the Seal
of the School / Institution

Principal
Mount Litera Zee School
Bhubaneswar

PART - II

(To be filled in the S.D.E.)

- a. I have visited the above mentioned school on dated 22/4/23 and have visually inspected it from all angles of safety and find it fit for normal use as School buildings.
- b. In case any addition / alteration or expansion and modification to this building is to be carried out under the supervision of a qualified Engineer and this certificate may be re-obtained after the completion from the undersigned.
- c. In case the building is affected by the flood, or if there is settlement of walls / foundation or sagging of the roofs etc. immediate inspection of the undersigned be arranged to check the stability and safety of the building.

S. Behera
22/4/23
Assistant Engineer
R.W. Sub-Division No-II
SEAL Bhubaneswar